


Waterproof Treatment

----LWW-5-36P-L1200

Reference pictures:



Operation Steps:

- 1.Coated the end cap with enough silica gel.
- 2.Twist tightly the swrews on the end cap.
- 3.Smear the silica gel on the gap of end cap.
- 4.Cover every screw with silica gel.
- 5.Stick up the light,make one end cap on the ground.
- 6.After 3-4 hours sealing time,change to the other end cap.

PS:Pls kindly notice that you must sealing well 1 end cap in advance, then turn to the operate the otherone, do not sealing 2 end caps at the same time,because silica gel is liquid type,when you stick up one end, the gel will flow down.